


POWERLINE



KEYED DIAGRAM FOR USE WITH SPARE PARTS LIST

- cription
- ch
 - chbox
 - ws (3)
 - le (UK only)
 - le clamp and screws (2)
 - le clamp and screw (1)
 - minimal block
 - ick release cover screw } Set
 - isher
 - otor screws
 - id (4)
 - ng nut (2)
 - m
 - ame and base complete
 - ade 8 t.p.i.
 - ade 14 t.p.i.
 - ade 24 t.p.i.
 - ade 32 t.p.i.
 - ade 3/8" 6 t.p.i.
 - ence